

FIGURE 1

Patent Office




FIGURE 2A






FIGURE 2C




FIGURE 3






FIGURE 5




FIGURE 6






FIGURE 7

Fig. 1 is a schematic diagram of a mechanical assembly. It shows a curved member 30 with a roller at one end, connected via a linkage 106 to a rotating component 108. This component is part of a larger assembly 110, which includes a curved member 31.

[illegible]

FIGURE 8






FIGURE 11




FIGURE 12




FIGURE 13




FIGURE 14




FIGURE 15






FIGURE 16




FIGURE 17




FIGURE 18




FIGURE 19A




FIGURE 19B




FIGURE 19C




FIGURE 19D




FIGURE 19D








FIGURE 19F